

Fire Alarm service and diagnoses

From: "Dale Johnson" <dale@dmmattson.com>

01/21/11 05:03 PM

To: ntipton@decatur.lib.il.us

Noah,

As per our conversations the cost to replace the 2 known failed components and diagnose the system faults will be \$2,388.27

This will include the following:

1. Materials for (1) failed Fire Alarm Control Panel Display (EST part number 2-LCD) and the (1) failed Control Relay (EST part number SIGA-CR)
2. (16) hours on site time by our fire alarm technician to replace the items listed above and to work towards diagnoses the faults on the fire alarm system

This labor will be treated as a service call to diagnose the sources of the existing fault conditions on this system.

All attempts will be made to rectify any conditions but we are not able to guarantee that any faults will be cleared in the (16) hours allotted.

We will fix all faults and conditions that we can in this time and make all efforts to diagnose any adverse conditions that we can.

Let me know if you have any questions,

Dale Johnson
Applications Engineer / Project Manager
D.M. Mattson, Inc
Mobile: 309-838-8231